

Leigh Dyer
8 West Street
Old Town
TN34 3AN

Maintenance Schedule for the Landing sculpture

Monthly assessments from the 14th October 2016 -14th October 2017
Assessments made by Leigh Dyer

Assessment list:

- Stone chip damage
- Fixing points of letters
- Alignment of the sculpture
- Weld joints
- Overall appearance

Expected changes to the surface of the sculpture due to weathering:

- Surface colour
- Surface rust
- Seagull droppings staining

Assessments required after October 2017 made by Hastings Borough Council

- Six monthly checks of the list above